United States Environmental Protection Agency Region VI POLLUTION REPORT

Date: Friday, February 23, 2007

From: Karen Mccormick

Subject: Continuation of Action

Central Crude LaFourche Spill 9793 Highway 308, Lockport, LA

Latitude: 29.5898200 Longitude: -90.4435500

POLREP No.: 2 **Site #:** NRC 827176

Reporting Period: 2/23/2007 **D.O.** #:

Start Date: 2/22/2007 Response Authority: OPA

Mob Date:2/22/2007Response Type:EmergencyDemob Date:NPL Status:Non NPL

Completion Date: Incident Category: Removal Action

CERCLIS ID #: Contract #

RCRIS ID #: Reimbursable Account #

FPN# E07607

Site Description

On February 22, 2007, the National Response Center was notified of an oil spill from a 26,000 barrel above ground storage tank (tank 9195) associated with the Central Crude Valentine Facility adjacent to Bayou Lafourche in Lockport, Lafourche Parish, Louisiana (NRC No. 827176). The facility address is 9793 Highway 308, Lockport, Louisiana. The spill was a result of the failure of a four inch flexible hose used to transfer crude oil from the oil storage tank through a pump into a pipeline. The facility operator began transferring oil from tank 9195 at 0130 hours on the morning of 22 February, 2007. The operator discovered spilled oil in tank 9195 secondary containment at 0530 on the same day. Oil from tank 9195 seeped from its secondary containment, into an adjacent tank's secondary containment through a storm water drainage valve. The oil then traveled to the secondary containment storm water discharge valve. The valve was closed, however; the soil surrounding the piping and valve leading from the interior of the secondary containment to an adjacent canal had eroded. This provided the oil a pathway from the secondary containment into the canal. The canal is approximately 400 feet long, and from the entrance of the drainage piping, it flows approximately 150 feet south into Bayou Lafourche. Oil from the facility entered Bayou Lafourche, a tidally influenced, navigable waterway of the United States. The operator terminated transfer of oil through the failed hose and notified the facility manager who activated the facility's response contractor, Environmental Safety and Health, Inc. (ES&H). The operator closed the valve between the secondary containment units, and placed onsite boom across the canal mouth in an attempt to prevent additional oil from reaching the bayou. The facility operator estimates that approximately 1,800 barrels (bbls) of crude oil was discharged through the broken hose, of which 1,600 bbls remained within the secondary containment units, 100 bbls was contained within the canal, and 100 bbls entered Bayou Lafourche. This estimate is greater than the initial estimate of 350 bbls. ES&H personnel arrived at the spill scene on February 22, 2007 at 0900 and initiated containment and recovery activities. The spill impacted the 400 feet of the canal and approximately 1.1 miles of Bayou Lafourche.

Due to the proximity of the spill to the United States Coast Guard MST 3 in Houma, LA and the impact to a navigable waterway, two USCG representatives, Petty Officers Hendry and Ariail, responded to the spill scene at 0830 on 22 February 2007. Upon arrival of EPA representatives, the USCG provided the representatives with a briefing of events and transferred oversight responsibilities to the EPA and departed the spill scene.

Current Activities

On 23 February 2007, EH&S continued recovery of oil from the service canal, and containment efforts of spilled oil in Bayou Lafourche by the deploying of containment and sorbent boom. EH&S deployed containment boom along the northern bank from the service canal entrance into the bayou to the furthest downstream boom, as well as sorbent on the outside of containment boom in heavily oiled areas. Bayou Lafourche was not able to be reopened to boat traffice, due to uncontained oil within the 1.1 mile containment area; the southeastern wind blew oil that was being held on the upstream side of the downstream boom upstream along the northern bank and into the center of the bayou. Mr. Pat Breaux, Louisiana Department of Environmental Quaility (LDEQ), and Mr. Roland Guidry, Louisiana Oil Spill Coordinator's Office (LOSCO), agreed with the Bayou staying closed for the time being. LDEQ Breaux did not note any impacted wildlife due to the oil spill. Mr. Vincent, Central Crude member, stated that they recovered approximatley 1,640 bbls of oil on 22 February 2007; 1,640 bbls was from the secondary containment aroungd storage tank 9195 and 40 bbls from the service canal. Central Crude began filling secondary containment around tank 9195 with water to float residual oil to the surface for recovery.

Planned Removal Actions

RP clean up contractors will continue containment, clean up and recovery operations. Projected completion date has not been established. ES&H will mobilize additional oil recovery and containment equipment to the site in the morning to assist oil spill response, and plan to reopen Bayou Lafourche once threat has been mitigated.

Next Steps

EPA representatives will return to the site on 24 February 2007 to document response activities and communicate that information to the OSC.

Key Issues

- •Spill affected Bayou Lafourche a tidally influenced navigable waterway of the US.
- •Shorelines of the bayou are comprised of cord grass and reeds making recovery of oil from the vegetated areas difficult.
- •Significant boat operations will be necessary for recovery.
- •The bayou has been closed to recreational and commercial boat traffic.
- •Potential for impact to wildlife.

www.epaosc.org/centralcrude